



**Ann Arbor Public Schools
Drinking Water Analysis
Project Number: AE240030**

Site: Haisley Elementary School									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: February 10, 2024									
Sampler: Maryn Burrell									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
Haisley-04	Staff Lounge, Combination Sink, Glass Filler	Combination Sink	9:05 AM	5	ND	N	Y	7/5/2022	
Haisley-09	Room 106, Combination Sink, Glass Filler	Combination Sink	8:25 AM	5	ND	N	Y	7/6/2023	
Haisley-13	Room 109, Right Combination Sink, Glass Filler	Combination Sink	8:10 AM	5	ND	N	Y	7/5/2023	
Haisley-18	Room 105, Combination Sink, Glass Filler	Combination Sink	8:15 AM	5	ND	N	Y	7/6/2023	
Haisley-24	Room 100, Combination Sink, Glass Filler	Combination Sink	8:20 AM	5	ND	N	Y	7/6/2023	
Haisley-30	Room 110, Combination Sink, Glass Filler	Combination Sink	8:30 AM	5	ND	N	Y	7/5/2022	
Haisley-37	Room 113, Combination Sink, Glass Filler	Combination Sink	8:35 AM	5	ND	N	Y	7/5/2023	
Haisley-40	Room 204, Combination Sink, Glass Filler	Combination Sink	8:40 AM	5	ND	N	Y	7/5/2023	
Haisley-46	Room 402, Combination Sink, Glass Filler	Combination Sink	8:50 AM	5	ND	N	Y	7/5/2023	
Haisley-52	Room 300, Combination Sink, Glass Filler	Combination Sink	8:55 AM	5	ND	N	Y	7/23/2024	
Haisley-58	Room 306, Combination Sink, Glass Filler	Combination Sink	9:00 AM	5	ND	N	Y	7/5/2023	
Haisley-66	Hallway, Outside Room 402, Hydration Station, Bottle Fill	Hydration Station	8:45 AM	5	ND	Y	N/A	N/A	
Haisley-67	Hallway Across Room 114, Hydration Station, Bottle Fill	Hydration Station	8:05 am	5	ND	Y	N/A	N/A	

*ND = Non-Detected at Reported Detection Limit of 1 ug/L