



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Pattengill Elementary School							
Date of Sampling: 10/27/2018							
Sampler: Lindsey Eveleth							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pattengill-01	Teachers Lounge, Kitchen Sink	KF	11:46 AM	5	10	Y	First Draw. Water Leaks from Base of Faucet.
Pattengill-02	Room C-4, Faucet	C	10:49 AM	5	1	Y	First Draw. Corrosion on Aerator/Faucet.
Pattengill-03	Hallway, Outside Room C-8, Bottle Fill, Water Cooler Outlet	BT	11:01 AM	5	ND <sup>3</sup>	N	First Draw.
Pattengill-04	Hallway, Outside Room A-1, Water Cooler	WC	11:07 AM	5	ND	N	First Draw. Corrosion on Mouthpiece.
Pattengill-05	Room A-4 Bubbler	C	11:30 AM	5	2	N	First Draw
Pattengill-06	Room A-6 Faucet	C	11:23 AM	5	2	Y	First Draw. Corrosion on Aerator.
Pattengill-07	Room A-8 Faucet	C	11:15 AM	5	1	Y	First Draw. Corrosion on Aerator.
Pattengill-08	Room A-4, Bubbler	C	11:17 AM	5	ND	N	First Draw
Pattengill-09	Room A-7, Bubbler	C	11:19 AM	5	2	N	First Draw
Pattengill-10	Room B-16 Faucet	C	12:32 PM	5	2	Y	First Draw
Pattengill-11	Room B-7 Faucet	C	12:10 PM	5	1	Y	First Draw
Pattengill-12	Hallway, Outside Room B-3, Bottle Fill, Water Cooler Outlet	BT	11:48 AM	5	ND	N	First Draw.
Pattengill -13	Media Center Kitchen, Faucet	KF	11:02 AM	5	3	Y	First Draw. Corrosion on Aerator/Faucet.
Pattengill -14	Hallway, Outside Room C-8, Bottle Fill Outlet	BT	11:00 AM	5	ND	N	First Draw
Pattengill -16	Cafeteria Kitchen, 3-Compartment, Faucet	KF	11:05 AM	5	4	Y	First Draw. Dripping Faucet.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Pattengill Elementary School							
Date of Sampling: 10/27/2018							
Sampler: Lindsey Eveleth							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pattengill -17	Hallway, Outside Room C-4, Bubblers	C	10:55 AM	5	ND	N	First Draw. Corrosion on Mouthpiece.
Pattengill -18	Hallway, Outside Room C-4, Faucet	C	10:53 AM	5	2	Y	First Draw. Corrosion on Aerator/Faucet.
Pattengill -19	Room C-4, Bubblers	C	10:51 AM	5	2	N	First Draw. Corrosion on Mouthpiece.
Pattengill -20	Hallway, Outside Room B-3, Bottle Fill Outlet	BT	11:50 AM	5	ND	N	First Draw
Pattengill -21	Kitchen Between Rooms B-19 and B-18, Kitchen Faucet	KF	12:46 PM	5	ND	Y	First Draw
Pattengill -22	Room B-3, Bubblers	C	11:54 AM	5	2	N	First Draw
Pattengill -23	Room B-3, Faucet	C	11:56 AM	5	ND	Y	First Draw
Pattengill -24	Room B-4, Bubblers	C	12:00 PM	5	ND	N	First Draw
Pattengill -25	Room B-4, Faucet	C	12:02 PM	5	1	Y	First Draw
Pattengill -26	Room B-5, Bubblers	C	12:04 PM	5	ND	N	First Draw
Pattengill -27	Room B-5, Faucet	C	12:06 PM	5	ND	Y	First Draw. Dripping Faucet.
Pattengill -28	Room B-6, Bubblers	C	12:08 PM	5	2	N	First Draw. Slow to Drain.
Pattengill -29	Room B-6, Faucet	C	12:09 PM	5	4	Y	First Draw. Slow to Drain.
Pattengill -30	Room B-7, Bubblers	C	12:12 PM	5	ND	N	First Draw. Low Flow.
Pattengill -31	Room B-8, Bubblers	C	12:14 PM	5	ND	N	First Draw
Pattengill -32	Room B-8, Faucet	C	12:16 PM	5	2	Y	First Draw
Pattengill -33	Room B-9, Bubblers	C	12:18 PM	5	2	N	First Draw

1) Type: B = Bubblers, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminants>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Pattengill Elementary School							
Date of Sampling: 10/27/2018							
Sampler: Lindsey Eveleth							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pattengill -34	Room B-9, Faucet	C	12:20 PM	5	4	Y	First Draw
Pattengill -35	Room B-11, Bubbler	C	12:22 PM	5	3	N	First Draw
Pattengill -36	Room B-11, Faucet	C	12:24 PM	5	6	Y	First Draw
Pattengill -37	Room B-12, Bubbler	C	12:27 PM	5	ND	N	First Draw. Dripping Bubbler.
Pattengill -38	Room B-12, Faucet	C	12:29 PM	5	2	Y	First Draw
Pattengill -39	Room B-16, Bubbler	C	12:34 PM	5	ND	N	First Draw. Low Flow.
Pattengill -40	Room B-17, Bubbler	C	12:37 PM	5	1	N	First Draw. Corrosion on Mouthpiece.
Pattengill -41	Room B-17, Faucet	C	12:39 PM	5	2	Y	First Draw. Corrosion on Aerator.
Pattengill -42	Room B-18, Bubbler	C	12:40 PM	5	ND	N	First Draw. Slow to Drain.
Pattengill -43	Room B-18, Faucet	C	12:42 PM	5	1	Y	First Draw. Slow to Drain.
Pattengill -44	Room A-2, Bubbler	C	11:40 AM	5	ND	N	First Draw
Pattengill -45	Room A-2, Faucet	C	NOT SAMPLED				Water Turned Off.
Pattengill -46	Room A-3, Bubbler	C	11:34 AM	5	ND	N	First Draw
Pattengill -47	Room A-3, Faucet	C	11:36 AM	5	ND	Y	First Draw. Corrosion on Aerator.
Pattengill -48	Room A-4, Faucet	C	11:32 AM	5	ND	Y	First Draw. Corrosion on Aerator.
Pattengill -49	Room A-5, Faucet	F	11:27 AM	5	2	Y	Water Leaks from Base of Faucet.
Pattengill -50	Room A-6, Bubbler	C	11:25 AM	5	3	N	First Draw. Low Flow.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested

Action Level >5ppb



Ann Arbor Public Schools  
 Lead Drinking Water Analysis  
 Project Number: AE180861

Pattengill Elementary School

Date of Sampling: 10/27/2018

Sampler: Lindsey Eveleth

Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pattengill -51	Room A-7, Faucet	C	11:21 AM	5	2	Y	First Draw
Pattengill -52	Room A-9, Bubbler	C	11:11 AM	5	ND	N	First Draw
Pattengill -53	Room A-9, Faucet	C	11:12 AM	5	1	Y	First Draw. Corrosion on Aerator.

Pattengill Elementary School

Date of Sampling: 4/19/2018

Sampler: Alec Staber

Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Pattengill-04	Hallway, Outside Room A-1, Hydration Station, Water Cooler	BF	12:06 PM	5	ND	N	First Draw. New Hydration Station.
Pattengill -15	Hallway, Outside Room A-1, Hydration Station, Bottle Fill	BF	12:01 PM	5	ND	N	First Draw. New Hydration Station.
Pattengill -54	Hallway, Outside Room A-7, Hydration Station, Water Cooler	BF	12:04 PM	5	ND	N	First Draw. New Hydration Station.
Pattengill -55	Hallway, Outside Room A-7, Hydration Station, Bottle Fill	BF	12:04 PM	5	ND	N	First Draw. New Hydration Station.
Pattengill -56	Hallway, Outside Room B-7, Hydration Station, Water Cooler	BF	12:07 PM	5	ND	N	First Draw. New Hydration Station.
Pattengill -57	Hallway, Outside Room B-7, Hydration Station, Bottle Fill	BF	12:07 PM	5	ND	N	First Draw. New Hydration Station.

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee  
 2) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante>  
 3) ND = Non Detected at Reported Detection Limit of 1 ug/L  
 4) NT = Not Tested