



**Ann Arbor Public Schools
Lead Drinking Water Analysis
Project Number: AE220030**

Carpenter Elementary School							
Date of Sampling: March 5, 2022							
Sampler: Zac Fortin							
Sample #	Location	Type ¹	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Carpenter-02	Room C-136, Combination Sink, Glass Filler	C	10:53 AM	5	ND ³	N	First Draw, Filtered.
Carpenter-05	Room C-141, Combination Sink, Glass Filler	C	10:57 AM	5	ND	N	First Draw, Filtered.
Carpenter-11	Room C-122, Combination Sink, Glass Filler	C	10:22 AM	5	ND	N	First Draw, Filtered.
Carpenter-13	Room C-110, Combination Sink, Glass Filler	C	10:42 AM	5	ND	N	First Draw, Filtered.
Carpenter-20	Room C-118, Combination Sink, Glass Filler	C	10:31 AM	5	ND	N	First Draw, Filtered.
Carpenter-27	Room C-117, Combination Sink, Glass Filler	C	10:35 AM	5	ND	N	First Draw, Filtered.
Carpenter-36	Kitchen, 2-Compartment Sink, Add On Faucet, Far Right Faucet, Kitchen Faucet	KF	10:16 AM	5	ND	Y	First Draw, Filtered.
Carpenter-48	Hallway, Across from Room C-136, Hydration Station, Bottle Fill	HS	10:47 AM	5	ND	Y	First Draw, Filtered.
Carpenter-53	Hallway, Outside Room C-119, Hydration Station, Bottle Fill	HS	10:28 AM	5	ND	Y	First Draw, Filtered.

- 1) Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, G = Glass Filler, WC = Water Cooler, C = Combination Sink,
- 2) PB = Potable Bathroom Faucet, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumbed Coffee Machine
- 3) <https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminant>
- 4) ND = Non Detected at Reported Detection Limit of 1 ug/L
- 5) NT = Not Tested

Action Level >5ppb